

Facility Summary in MINERAL County in the City of ALBERTON

Location: MOUNTAIN WEST CO OP ALBERTON
415 RAILROAD AVE
ALBERTON, MT 59820 MINERAL

Sys Fac ID: 56-13785

Last Inspected On: 2/1/2016

Operating Permit Renewal Date: 4/30/2019

Contact: (406) 543-8383

Owners/Operators: Mountain West Coop - Missoula, Owner

(406)-543-8383 4570 N RESERVE ST
MISSOULA MT 59808-1411

Will Dukart, UST Class A Operator
Dave Otto, UST Class A Operator
John Thompson, UST Class A Operator
Will Dukart, UST Class B Global Operator
Dave Otto, UST Class B Global Operator
John Thompson, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	18	8/1/1997	Bare Steel	Fiberglass Reinforced Plastic	
3858	Yes		None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Gasoline			Deferred	MLLD Line Tightness Testing	
12,000		1/20/2016			
2	18	8/1/1997	Bare Steel	Fiberglass Reinforced Plastic	
3859	Yes		None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Diesel			Deferred	MLLD Line Tightness Testing	
12,000		1/20/2016			
3	18	8/1/1997	Bare Steel	Fiberglass Reinforced Plastic	
3860	Yes		None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Diesel			Deferred	MLLD Line Tightness Testing	
10,000		1/20/2016			
4	18	8/1/1997	Bare Steel	Fiberglass Reinforced Plastic	
3861	Yes		None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Gasoline			Deferred	MLLD Line Tightness Testing	
4,000		1/20/2016			

Facility Summary in MINERAL County in the City of HAUGAN

Location: SILVER EXPRESS EXXON
EXIT 16 & INTERSTATE 90
HAUGAN, MT 59842 MINERAL

Sys Fac ID: 31-13289

Last Inspected On: 5/16/2013

Operating Permit Renewal Date: 8/28/2016

Contact: Brenda Lincoln, (406) 678-4242

Owners/Operators: Silver Dollar Ventures Inc, Owner (406)-678-4242 PO BOX 420038
HAUGAN MT 59842-0038
Brooke Lincoln, UST Class A Operator
Brooke Lincoln, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	21	4/1/1994	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
3161			None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Gasoline			Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
8,000		5/10/2013			
2	21	4/1/1994	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
3162			None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Gasoline			Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
6,000		5/10/2013			
3	21	4/1/1994	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
3163			None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Diesel			Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
12,000		5/10/2013			
4	21	4/1/1994	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
3164			None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Gasoline			Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
10,000		5/10/2013			

Facility Summary in MINERAL County in the City of SAINT REGIS

Location: SAINT REGIS EXXON
MULLAN ROAD & MT HIGHWAY 135 N
SAINT REGIS, MT 59866 MINERAL

Sys Fac ID: 31-05827

Last Inspected On: 3/26/2014

Operating Permit Renewal Date: 6/3/2017

Contact: Gary Bullock, (406) 649-2407

Owners/Operators: Lincoln Development Co Inc, Owner

(406)-649-2407

DBA ST REGIS EXXON EXPRESS
PO BOX 190
SAINT REGIS MT 59866-0190

Gary Bullock, UST Class A Operator

Gary Bullock, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	43	1/1/1973	Bare Steel	Steel	Flapper Valve (Auto Shutoff)
3630			Impressed Current	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Impressed Current
Diesel		5/27/2011	Stat. Inventory Reconciliation	Stat. Inventory Reconciliation	
8,000					
2	33	4/22/1982	Bare Steel	Steel	Flapper Valve (Auto Shutoff)
3631			Impressed Current	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Impressed Current
Gasoline		5/27/2011	Stat. Inventory Reconciliation	Stat. Inventory Reconciliation	
10,000					
3	33	4/22/1982	Bare Steel	Steel	Flapper Valve (Auto Shutoff)
3632			Impressed Current	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Impressed Current
Gasoline		5/27/2011	Stat. Inventory Reconciliation	Stat. Inventory Reconciliation	
10,000					
4	42	4/23/1973	Bare Steel	Steel	Flapper Valve (Auto Shutoff)
3633			Impressed Current	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Impressed Current
Gasoline		5/27/2011	Stat. Inventory Reconciliation	Stat. Inventory Reconciliation	
6,000					

Facility Summary in MINERAL County in the City of SAINT REGIS

Location: STANGS INC
12 OLD US HIGHWAY 10 E
SAINT REGIS, MT 59866 MINERAL
Contact: Richard Stang, (406) 649-2414

Sys Fac ID: 31-07503
Last Inspected On: 5/23/2013
Operating Permit Renewal Date: 9/7/2016

Owners/Operators: Stangs Inc, Owner (406)-649-2414 PO BOX 340
SAINT REGIS MT 59866-0340
Richard L Stang, UST Class A Operator
Richard L Stang, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
5	16	8/1/1999	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
4105			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline			Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	
6,000					
6	16	8/1/1999	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
4106			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline			Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	
6,000					
7	16	8/1/1999	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
4107			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline			Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	
6,000					

Facility Summary in MINERAL County in the City of SAINT REGIS

Location: SAINT REGIS TRAVEL CENTER
100 MULLAN ROAD W
SAINT REGIS, MT 59866 MINERAL
Contact: Gary Bullock, (406) 649-2407

Sys Fac ID: 31-07690
Last Inspected On: 3/26/2014
Operating Permit Renewal Date: 3/28/2017

Owners/Operators: Lindevco Inc, Owner (406)-649-2407 PO BOX 190
SAINT REGIS MT 59866-0190
Gary Bullock, UST Class A Operator
Gary Bullock, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	30	4/22/1985	Cathodically Protected Steel	Steel	Flapper Valve (Auto Shutoff)
3813			Lined Interior/Impressed Current	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Impressed Current
Gasoline		5/27/2011	Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
12,000		10/30/2014	TLS-350/Gilbarco EMC , Veeder Root		
3	30	4/22/1985	Cathodically Protected Steel	Steel	Flapper Valve (Auto Shutoff)
3814			Lined Interior/Impressed Current	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Impressed Current
Diesel		5/27/2011	Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
12,000		10/30/2014	TLS-350/Gilbarco EMC , Veeder Root		
4	30	4/22/1985	Cathodically Protected Steel	Steel	Flapper Valve (Auto Shutoff)
3815			Lined Interior/Impressed Current	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Impressed Current
Gasoline		5/27/2011	Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
6,000		10/30/2014	TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in MINERAL County in the City of SALTESE

Location: TAFT SUBSTATION
RANDOLPH CREEK RD
SALTESE, MT 59867 MINERAL

Sys Fac ID: 31-07747

Last Inspected On: 6/19/2013

Operating Permit Renewal Date: 8/18/2016

Contact: Ken Owen, (406) 257-4385

Owners/Operators: Bonneville Power Administration Kalispell, Owner (406)-751-7800 2520 US HIGHWAY 2 E
KALISPELL MT 59901-2312
Emery Barnhill, UST Class A Operator
Emery Barnhill, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
3	25	10/1/1990	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve (Auto Shutoff)
478		6/9/2013	Double-Walled	Secondary Containment Chase	Yes
Currently in Use			Continuous Interstitial Monitoring	Safe Suction	Not Applicable
Diesel			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Not Listed	
10,000				Continuous Interstitial Monitor	

Facility Summary in MINERAL County in the City of SUPERIOR

Location: MINERAL COUNTY COURTHOUSE UST
300 RIVER ST
SUPERIOR, MT 59872 MINERAL

Sys Fac ID: 31-02302

Last Inspected On: 2/4/2015

Operating Permit Renewal Date: 7/25/2018

Contact: Sam Viche, (406) 822-3525

Owners/Operators: Mineral County Health Dept, Owner

(406)-822-4632

PO BOX 396
SUPERIOR MT 59872-0396

Roy Kay, UST Class A Operator

Roy Kay, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	21	5/1/1994	Cathodically Protected Steel	Flexible Plastic	Flapper Valve (Auto Shutoff)
4450		2/4/2015	Double-Walled	Double-Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Galvanic
Heating Oil		2/9/2015	Continuous Interstitial Monitor	Continuous Interstitial Monitor	
5,000			ILS-350 , Veeder Root		

Facility Summary in MINERAL County in the City of SUPERIOR

Location: DURANGOS INC
204 4TH AVE E
SUPERIOR, MT 59872 MINERAL

Sys Fac ID: 31-07433

Last Inspected On: 2/10/2015

Operating Permit Renewal Date: 4/26/2018

Contact: Joseph Hendrick, (406) 822-4967

Owners/Operators: Jo-Joe Investments, Owner (406)-822-4967 PO BOX 413
SAINT REGIS MT 59866-0413
Jolie Skelton, UST Class A Operator
Jolie Skelton, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	31	4/23/1984	Cathodically Protected Steel	Steel	Positive Shutoff
3816			Lined Interior/Impressed Current	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Impressed Current
Gasoline		2/9/2015	Stat. Inventory Reconciliation	MLLD Line Tightness Testing	
10,000		2/9/2015		Stat. Inventory Reconciliation	
2	31	4/23/1984	Cathodically Protected Steel	Steel	Positive Shutoff
3817			Lined Interior/Impressed Current	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Impressed Current
Gasoline		2/9/2015	Stat. Inventory Reconciliation	MLLD Line Tightness Testing	
10,000		2/9/2015		Stat. Inventory Reconciliation	

Facility Summary in MINERAL County in the City of SUPERIOR

Location: TOWN PUMP INC SUPERIOR
3961 DIAMOND MATCH RD
SUPERIOR, MT 59872 MINERAL
Contact: Trent Biggers, (406) 497-6700

Sys Fac ID: 31-08719
Last Inspected On: 1/29/2013
Operating Permit Renewal Date: 5/14/2016

Owners/Operators: Town Pump of Superior Inc, Owner (406)-497-6700 PO BOX 6000
BUTTE MT 59702-6000
Trent Biggers, UST Class A Operator
Trent Biggers, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	46	1/22/1970	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
2538			Lined Interior/Impressed Current	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		9/17/2014	Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
10,000					
2	46	1/22/1970	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
2539			Lined Interior/Impressed Current	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Diesel		9/17/2014	Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
6,000					
3	30	1/1/1986	Cathodically Protected Steel	Flexible Plastic	Ball Float Valve
2540			Lined Interior/Impressed Current	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Impressed Current
Diesel		9/17/2014	Stat. Inventory Reconciliation, Approved Remote Monitoring	Continuous Interstitial Monitor, Stat. Inventory Reconciliation, Approved Remote Monitoring	
12,000					

Facility Summary in MINERAL County in the City of SUPERIOR

Location: TOWN PUMP INC SUPERIOR
3961 DIAMOND MATCH RD
SUPERIOR, MT 59872 MINERAL

Sys Fac ID: 31-08719
Last Inspected On: 1/29/2013
Operating Permit Renewal Date: 5/14/2016

Contact: Trent Biggers, (406) 497-6700

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
4	44	1/1/1972	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
2541			Lined Interior/Impressed Current	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		9/17/2014	Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
12,000					
5	35	1/1/1981	Cathodically Protected Steel	Flexible Plastic	Ball Float Valve
4840			Lined Interior/Impressed Current	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Impressed Current
Diesel		9/17/2014	Stat. Inventory Reconciliation, Approved Remote Monitoring	Continuous Interstitial Monitor, Stat. Inventory Reconciliation, Approved Remote Monitoring	
12,000					
6	27	1/1/1989	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
2543			None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Diesel		2/20/2010	Stat. Inventory Reconciliation, Approved Remote Monitoring	Continuous Interstitial Monitor, Stat. Inventory Reconciliation, Approved Remote Monitoring	
12,000					
7	27	1/1/1989	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
4841			None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Diesel		2/20/2010	Stat. Inventory Reconciliation, Approved Remote Monitoring	Continuous Interstitial Monitor, Stat. Inventory Reconciliation, Approved Remote Monitoring	
10,000					

Facility Summary in MINERAL County in the City of SUPERIOR

Location: TOWN PUMP INC SUPERIOR
3961 DIAMOND MATCH RD
SUPERIOR, MT 59872 MINERAL

Sys Fac ID: 31-08719

Last Inspected On: 1/29/2013

Operating Permit Renewal Date: 5/14/2016

Contact: Trent Biggers, (406) 497-6700

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
8	12	6/9/2003	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
4842			Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Diesel		2/20/2010	Continuous Interstitial Monitor, Stat. Inventory Reconciliation, Approved Remote Monitoring	Continuous Interstitial Monitor, Stat. Inventory Reconciliation, Approved Remote Monitoring	
8,000					
9	12	6/9/2003	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
4843			Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Diesel		2/20/2010	Continuous Interstitial Monitor, Stat. Inventory Reconciliation, Approved Remote Monitoring	Continuous Interstitial Monitor, Stat. Inventory Reconciliation, Approved Remote Monitoring	
3,000					

Facility Summary in MINERAL County in the City of SUPERIOR

Location: MOUNTAIN WEST CO OP SUPERIOR
211 RIVER ST
SUPERIOR, MT 59872 MINERAL

Sys Fac ID: 31-08916

Last Inspected On: 2/2/2016

Operating Permit Renewal Date: 4/30/2019

Contact: Thompson Chuck, (406) 543-8383

Owners/Operators: Mountain West Coop - Missoula, Owner

(406)-543-8383

4570 N RESERVE ST
MISSOULA MT 59808-1411

Will Dukart, UST Class A Operator

Dusty Smith, UST Class A Operator

John Thompson, UST Class A Operator

Will Dukart, UST Class B Global Operator

Dusty Smith, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
3	29	5/1/1986	Cathodically Protected Steel	Flexible Plastic	Ball Float Valve
1063			None	Double-Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Galvanic
Diesel		2/1/2016	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
2,000		1/14/2016	Gilbarco EMC Basic , Gilbarco		
4	29	5/1/1986	Cathodically Protected Steel	Flexible Plastic	Ball Float Valve
1064			None	Double-Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Galvanic
Gasoline		2/1/2016	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
2,000		1/14/2016	Gilbarco EMC Basic , Gilbarco		
5	29	5/1/1986	Cathodically Protected Steel	Flexible Plastic	Ball Float Valve
1065			None	Double-Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Galvanic
Diesel		2/1/2016	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
2,000		1/14/2016	Gilbarco EMC Basic , Gilbarco		

Facility Summary in MINERAL County in the City of SUPERIOR

Location: S & S FOODS INC 3112870
205 4TH AVE E
SUPERIOR, MT 59872 MINERAL
Contact: Dale Bullock, (406) 822-4837

Sys Fac ID: 31-12870
Last Inspected On: 7/22/2013
Operating Permit Renewal Date: 9/25/2016

Owners/Operators: D and T Properties LLC, Owner (406)-822-3342 PO BOX 158
SUPERIOR MT 59872
Dale Bullock, Operator (406)-822-3342 209 PINE STREET
SUPERIOR MT 59872
Gary Bullock, UST Class A Operator
Gary Bullock, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	23	10/1/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
1971			None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Diesel			Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
3,000		7/19/2013			
2	23	10/1/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
1970			None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Gasoline			Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
6,000		7/19/2013			
3	23	10/1/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
1968			None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Gasoline			Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
8,000		7/19/2013			
4	23	10/1/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
1969			None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Gasoline			Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
4,000		7/19/2013			